

Equipment Required

Auto-scrubber

Ultra High Speed Burnisher (electric or propane gas)

Mops; buckets; dust catch mop; polish applicator and floor maintenance pads

Always keep the storeroom floor clean to reduce the amount of dirt tracked back onto the clean floor.

Stripping & Polish Application

1. Dust mop the entire floor area
2. Use Actichem's AP404 Power Strip @ 1:4 in a mop and bucket.
3. Liberally apply solution to floor area with a mop. Allow 5-10 minutes dwell time. Ensure that the solution does not dry on the floor during this time.
4. Scrub with auto-scrubber or low speed buffer and black pads. Detail edges with edging tool.
5. Apply clean water with auto-scrubber and pick up dirty solution with auto-scrubber or wet/dry vacuum. Rinse floor a second time using clean water and a clean mop to ensure that no residue is left behind.
6. Buff the entire floor area with high-speed burnisher and follow up with dust catch mop.
7. Apply one even coat of AP420 Instaseal. Coverage is approximately 40m² per litre.
8. Once dry, apply three even coats of AP424 Instaglaze. Coverage is approximately 50m² per litre.
9. Should the floor require additional finish, allow at least 24 hours drying/curing time, then wet clean the floor, buff lightly and mop entire floor area with dust catch mop before applying two further coats of AP424 Instaglaze.
- 10. After 2 weeks the floor can be cut back and re-coated. This will improve gloss and wear.**

Daily Maintenance

1. Dust mop entire floor area
2. Scrub floor with auto-scrubber and a red floor maintenance pad. Use AP412 Instabuff Super as a spray buff, or AP662 Proneutro for general cleaning (1:200 in auto-scrubber).
3. Trail clean rinse mop behind auto-scrubber.
4. Buff floor with Ultra High Speed burnisher.
5. Dust mop floor.

Cutting back & Re-coating

1. Dust mop entire floor area
2. Scrub floor with auto-scrubber and a red floor maintenance pad. Use AP662 Proneutro (1:200 in auto-scrubber).
3. Trail clean rinse mop behind auto-scrubber.
4. Buff floor with Ultra High Speed burnisher, followed by dust catch mop.
5. Apply two coats of AP424 Instaglaze
6. Burnish second coat with light pad when touch dry.